



Ultimate Client Manager

# TAX INVOICE

**ABN:** 12 345 678 912  
**Email:** your@company.com  
**Web:** www.company.com

**Invoice No:** 160202  
**Invoice Date:** 02/02/2016  
**Due Date:** 03/03/2016  
**Paid Date:**

## RECIPIENT

**Company:** Bettles  
**Contact:** Marty Bettles  
**Phone:**

**Email:** marty.bettles@interactmedical.co.uk  
**Project:**  
**Job:** bob

## INVOICE DETAILS

#	Description	Date	Qty	Amount	Sub-Total
1	Chemicals > Chlorine Granules 1kg <i>Chlorine Granules 1kg. Chlorine sanitiser. Add a capful or two as indicated by test strip readings. Add with pumps running, leave cover open for 15 minutes to allow off gas to escape.</i>	02/02/2016	1	£9.99	£9.99
2	Chemicals > 3 Way Test Strips 50 <i>3 Way Test Strips (Pack of 50). Use on a daily basis to test your spa and determine what chemicals to add to bring levels to an acceptable range.</i>	02/02/2016	1	£10.99	£10.99
3	Filters > CS100 <i>CS100 Filter for Coast Spas</i>	02/02/2016	1	£59.99	£59.99
4	1kg Chlorine	02/02/2016	-	£60.00	£0.00
5	Chemicals > Chlorine Granules 1kg <i>Chlorine Granules 1kg. Chlorine sanitiser. Add a capful or two as indicated by test strip readings. Add with pumps running, leave cover open for 15 minutes to allow off gas to escape.</i>	02/02/2016	1	£9.99	£9.99
6	Chemicals > Chlorine Granules 1kg <i>Chlorine Granules 1kg. Chlorine sanitiser. Add a capful or two as indicated by test strip readings. Add with pumps running, leave cover open for 15 minutes to allow off gas to escape.</i>	02/02/2016	1	£9.99	£9.99
7	Chemicals > 3 Way Test Strips 50 <i>3 Way Test Strips (Pack of 50). Use on a daily basis to test your spa and determine what chemicals to add to bring levels to an acceptable range.</i>	02/02/2016	1	£10.99	£10.99

#	Description	Date	Qty	Amount	Sub-Total
	Services > Full Service LOCAL Full Hot Tub Service (recommended annually). WITHIN 25 MILES SHOWROOM Bacteriacide pipe flush to remove biofilm and any calcium build up form pipework. Full Component Check and Amperage Readings taken, any recommendations made Pipework and glue joint inspection.				
8	Rinse filters and advise on condition and replacement timescale. Drain, rinse, Hoover spa of existing water. Check heater element free of scale, inspect and tighten all unions. Check all jets and clean. Shell cleaned, refilled with fresh water, cabinet and steps cleaned, cover polished Water shocked and set to desired temperature.	02/02/2016	-	£250.00	£250.00

Sub Total:	£361.94
VAT 20%	£72.39
<b>Total:</b>	<b>£434.33</b>

Paid:	£0.00
<b>Due:</b>	<b>£434.33</b>

## PAYMENT

### Option #1: Pay Online

We support the following secure payment methods:

- **Google Checkout**
- **PayPal**

Please [click here](#) to pay online.

### Option #2: Pay Offline

We support the following offline payment methods:

- **Bank Transfer**  
Bank Name: **Name Here**  
Bank Account: **123456**  
Payment Reference: **160202**  
Amount: **£434.33**
- **Other**  
Payable To: **Name Here**  
Post To: **123 Your Address, LA**  
Amount: **£434.33**